

RECEIVED FROM

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080092-2

Cook Nichols Co.

DATE REC'D 12-17-36

P. O. NO. 6314

VENDOR PACKING SLIP NO. 800479

ACCT. OR

R. W. O. NO.

S. O. NO.

CHARGE TO

CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	REMARKS
QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION						QUANTITY	
							ACCEPTED	REJECTED
100		Disconnect Splice TLP #3-23 322-000000-1016-0-00-00-00-02 731302-17					100	
20		Lamp, G. E. Cat #90 12-18 VAC 331302-20 322-000000-1017-0-0-00-00-02					30	

RECEIVED BY Jordan

INSPECTED BY

Date 1/3/59

REJECTS RETURNED
ON SHIP. MEMO NO.RECEIVING INSPECTION REPORT
HYCON MFG. COMPANY
2961 E. COLORADO ST., PASADENA, CALIF.

No 127853

RECEIVED FROM

DATE REC'D 12-18-36

P. O. NO. 6314

VENDOR PACKING SLIP NO. 800479

ACCT. OR

R. W. O. NO.

S. O. NO.

CHARGE TO

QUANTITY
RECEIVED

Ricelin Electronic Inc.

CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	REMARKS
QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION						QUANTITY	
							ACCEPTED	REJECTED
50		Diode, Germanium 1AN92 730143-2 (800000-1017)		0	0	0	00	50

RECEIVED BY

INSPECTED BY

Date 1/3/59

REJECTS RETURNED

ON SHIP. MEMO NO.

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080092-2